

# Tailings Ponds


## Maracás Menchen Mine

**Below is a list of frequently asked questions regarding the tailings ponds at our Maracás Menchen Mine located in Bahia, Brazil.**

---

**1. What is the design type of the tailings ponds at the mine – upstream, center-line or downstream build?**

**A:** The design type used at the Maracás Menchen Mine is a pond rather than a conventional dam. Provided in the image below are specific facts about the design of our tailings ponds.



**2. When were the tailings ponds last certified by an independent safety inspector?**

**A:** Every 6 months an independent inspector evaluates the tailings ponds. The last inspection was in March 2021 and another inspection is scheduled for September 2021. All inspections are downloaded and available to view on the ANM (Brazilian Mining Department) website. ANM also completes inspections of the entire mine site at least once a year and the last inspection was in February 2021.

**3. Do you have a tailings manager on staff?**

**A:** The mine manager is in charge of the inspection and maintenance of the tailings ponds. There is also a full-time engineer responsible for the ponds.

**4. Is there an external Engineer of Record? If yes, when did he/she last sign off on the ponds?**

**A:** Yes. The initial design and construction of the project was completed by an external engineer who is also responsible for the inspection of the tailings ponds every 6 months. The last inspection was in March 2021.

**For further questions, please contact Alex Guthrie, Senior Manager, External Relations at [info@largoresources.com](mailto:info@largoresources.com).**